INDEX

PROCEEDINGS OF THE AMERICAN CONCRETE INSTITUTE

VOLUME 38—1942

From JOURNAL OF THE AMERICAN CONCRETE INSTITUTE, Vol. 13, Sept. 1941, to June 1942 and Supplement, November 1942.

This is an Index of:

Original contributions to the JOURNAL OF THE AMERICAN CONCRETE INSTITUTE—papers, reports, discussions by subject, title and author.

For the convenience of the reader who is referring to JOURNAL issues rather than to Bound Volumes (in which discussion is assembled following the paper discussed) there is a reference to JOURNAL issue in which discussion appeared. This reference to discussion is by supplementary page numbers. If the last page of a paper is 28, the first page of the discussion, published later, is 28 - 1.

In general, important subjects are classified and indexed under approximately 30 main headings each one appearing in its proper alphabetical order in bold face capital letters—as for instance, ARCHITECTURAL DESIGN. "Housing," and other subjects classified under this head, are indented.

Key words to important subjects, appear, in alphabetical order in addition to the general classification—as for instance "Admixtures" and "Aggregates" each referring to MATERIALS AND TESTS under which all allied references appear, indented. Authors' names and original titles of papers appear in bold face type in proper alphabetical sequence with the subjects, with references to their contributions.

Specific data on Beams are so indexed by reference to ENGINEERING DESIGN or TESTS OF MEMBERS AND COMPLETED STRUCTURES thus avoiding an oversight by the searcher of important allied data.

The complete title of each paper is indexed. This title is repeated in full following the name of the author in its proper alphabetical order. Numerous cross references to parts of the subject matter covered, do not always indicate the full scope. This may be found by looking up the item referred to under the name of the author.

The readiest use may be made of this index by gaining some familiarity with the main classifications as follows:

ARCHITECTURAL DESIGN
BIBLIOGRAPHIES
BREAKWATERS—DOCKS AND SEA WALLS
BRIDGES
BUILDING CODES
BUILDINGS
BUILDING UNITS
CENTRAL MIXING
COMMITTEES
CONSTRUCTION—DETAILS, METHODS AND COSTS
CURING
DAMS
DURABILITY
ENGINEERING DESIGN
FAILURES
FIRES, FIRE TESTS AND FIREPROOFING
LAWS AND PROPERTIES
MASONRY UNITS
MATERIALS AND TESTS
MIXTURES
PAVEMENT
PERMEABILITY
PIPE
PRECAST UNITS
RAILWAY USES
RESEARCH
RESERVOIRS AND TANKS
SEWERS
SPECIFICATIONS
STRUCTURAL MEMBERS
SURFACES
TESTS AND FIELD CONTROL
TESTS OF MEMBERS AND COMPLETED STRUCTURES
VIBRATION
WATER WORKS

A

Abeles, Paul W.—Disc. Tests of reinforced concrete beams with recommendations for attaining balanced design (June '42 Jl.) 80–1
Absorption—Control of volume changes. Swayze 425
Absorptive form lining. Vidal, Blanks 253
—Disc. Conv. Mr. Blanks responds to questions. (June '42 Jl.) 268–1
ACI Code's test load requirement. (JPP 38–96) Richart 476
Adopting the ACI code by reference. (JPP 38-97) Thompson 477
Air content of fresh concrete—Vacuum method of measuring. Pigman 121
Allbright, Edwin F.—Disc. Saving steel in reinforced concrete design. (Suppl. '42) 288–37
Aluminum powder—Effect on bond to reinforcing steel. McMillan (JPP 38-78) 183
Aluminum powder—Effect on durability. (JPP 38-79) Carlson 174, 274
Aluminum powder to increase bond of concrete to reinforcing steel. (JPP 38-78) McMillan 183
American Concrete Institute Publications Policy 1
Anderegg, F. O.—Disc. Good Practice in concrete masonry wall construction. (Suppl. '42) 328–1
Anderson, Kenneth A. (with Hughes)—Observations on the durability of dry tamped silo staves 237
Andersen, Paul—Design diagrams for square concrete columns eccentrically loaded in two directions 149
Architectural concrete on the new Naval Medical Center. Fischer 289

ARCHITECTURAL DESIGN

Finish—Exposed aggregate—Naval Medical Center. Fischer 289
Autoclave test—reaction between cement and aggregate. Stanton, Porter, Meder, Nicol 209
Autogenous Volume Change. Swayze 425

B

Balanced design—Rectangular beams. Cox 65
Ball, Donald G. (with Parks and Protze) —Disc. ACI Manual of Concrete Inspection—Report of Com. 611 (Suppl. '42) 541
Bars to resist bond failures (JPP 38-74) Gilkey 82
Belt transportation—Effect on concrete aggregate grading. Williams 329
Bertin, R. L.—Saving steel in reinforced concrete design 281
—Disc. (Suppl. '42) 288–37

BIBLIOGRAPHIES

Design—Beams—Flexure. Cox 65
Durability—Disintegration. Hughes, Anderson 237
Earthquake stresses in frame structures. Glover 453
Flow—Creep under sustained load. Pickett 333
Form lining—Absorptive. Blanks, Vidal ... 253
Volume changes—Control. Swayze 38
Blanks, R. F. (with Vidal)—Absorptive Form Lining 253
—Disc. (June '42 Jl.) 268–1
—Concreting in the rain. (JPP-38-87) ..... 358 (Chairman, with Vidal, Secy.)
—Proposed recommended practice for the design of concrete mixes. Report Com. 613 193
—Disc. (June '42 Jl.) 208–1
Bleeding—Causes and control. (JPP 38-93). Powers 473
Bleeding—Control of volume changes. Swayze 425
Boden, O. G.—Canal lining cured by sprayed coats of white-pigmented compound 449
—Machine methods for trimming subgrade and placing concrete canal lining 177
—Transit mixers used effectively on the Contra Costa Canal 269
—Canal lining cured by sprayed coats of white-pigmented compound 449
Bond of flat steel reinforcing. (JPP 38-86) Gilkey 357
Bond stress in concrete pull-out specimens. Watstein 37
—Disc. Friberg (June '42 Jl.) 52–1
Britzius, C. W.—Disc. Proposed recommended practice for the design of concrete mixes. Report of Com. 613 (June '42 Jl.) 208–1

BUILDING CODES

ACI Building Regulations (JPP 38-97) Thompson 477
ACI test load requirements. (JPP 38-96) Richart 476
National emergency code—Saving steel. Bertin 281
Walls—Airplane motor test building. (JPP 38-94) 474

C

California experience with the expansion of concrete through reaction between cement and aggregate. Stanton, Porter, Meder, Nicol 209
—Disc. Meissner, Rhoades, Tuthill, Carlson, Scholer, Davis, Witt, Stanton (Suppl. '42) 236–1
Canal lining cured by sprayed coats of white-pigmented compound. Boden ... 449
Canal lining—Machine methods for trimming subgrade and placing lining. Boden 177

Carlson, Roy W.—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42)..... 236–1
—Effect of aluminum powder on durability of concrete. (JPP 38-79).....184, 274
—Determining cement content of hardened concrete. (JPP 38-98)..... 477
—Disc. Effect of change in moisture-content of the creep of concrete under a sustained load. (Suppl. '42)..... 356–1
—Placing cold concrete in hot weather. (JPP 38-102)..... 524
—Shrinkage of concrete. (JPP 38-91)..... 363
Causes and control of bleeding. (JPP 38-93) Powers..... 473
CENTRAL MIXING
Transit—Canal lining. Boden..... 269
Cohen, A. Burton—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42)..... 541
Cold concrete in hot weather. (JPP 38-102) Carlson..... 524
Collins, H. G.—Some details in designing and mixing concrete. (JPP 38-84)..... 276
Committee 319 report—Proposed recommended practice for use of metal supports for reinforcement. Zabriskie..... 173
Committee 611 report—Manual of Concrete Inspection. Kelly. (Separate publication July 1941)
—Disc. Cohen, Crum, Julian, Thomson, Waugh, Protze, with Parks, and Ball, Goldbeck, Schnarr, Swayze, Farmer, Kelly. V. 38, p. 541 (Suppl. '42)..... 541
Committee 613 report—Proposed recommended practice for the design of concrete mixes. Blanks, Vidal..... 193
—Disc. Powers, Larson, Price. (Jan. '42 Jl.)..... 202
—Disc. Conv.: Blanks, Powers, Larson, Britzius, Hurlburt, Irwin; since the conv., Witt, Foresman, Ruettgers. (June '42 Jl.)..... 208–1
Committee 614 report—Proposed recommended practice for measuring, mixing, and placing concrete. Tuthill..... 93
—Disc. Foresman, Tuthill (June '42 Jl) 120-1
Com. 616 report—Nature of portland cement paints and proposed recommended practice for their application to concrete surfaces. Copeland..... 485
Com. 704 report—Proposed specification for cast stone. Walker..... 313
—Disc. Conv. Walker (June '42 Jl.). 316–1
—Disc. Tucker, Horn, Walker (Suppl. '42)..... 316–9
Comparison of reinforced concrete tied column formulas. (JPP 38-77) Willson. 181
Computing stirrup spacing in non-rectangular shear diagrams. (JPP 38-99) Goodwin..... 478
Concrete curing compound—made on the job. (JPP 38-100) Jones..... 521
Concrete failure attributed to aggregate of low thermal coefficient. Pearson 29
—Disc. Conv. Pearson, Hornibrook, Meissner, Young, Kellam, Davis, Withey, Swayze, Walker; since conv. Reagel and Willis, Pearson. (June '42 Jl.)..... 36–1
Concrete of the future. (JPP 38-101) Davis..... 523
Concrete laundry tray manufacture. (JPP 38-75)..... 82
Concrete specifications and water content of concrete. Warberg..... 169
Concreting in the rain. (JPP 38-87) Blanks..... 358

CONSTRUCTION—DETAILS, METHODS AND COSTS
Canal lining—Machine method of placing. Boden..... 177
—Mixing. Boden..... 269
Column forms—Fabricating and erecting (JPP 38-81)..... 273
Curing—Canal lining—sprayed compound. Boden..... 449
—Compound—made on job. (JPP 38-100) Jones..... 521
Forms—Absorptive lining. Vidal, Blanks.. 253
Inspection—Specifications and water content. Warberg..... 169
Laundry trays—manufacture (JPP 38-75).. 82
Masonry walls—Reinforcing (JPP 38-73) Kaiser..... 81
Measuring, Mixing and placing—Com. 614 report. Tuthill..... 93
Metal supports for reinforcement. Zabriskie. Report of Com. 319..... 173
Mixing plant—Aggregate transportation.... 329
Pavement—strengthening with mud jack. (JPP 38-95) Poulter..... 475
Placing—Cold concrete in hot weather. (JPP 38-102). Carlson..... 524
—in rain. (JPP 38-87) Blanks..... 358
—reinforcing steel. (JPP 38-89)..... 360
Stucco—Time interval between successive coats. (JPP 38-80) Kaiser..... 184
Walls—Good practice in concrete masonry Tippy..... 317
Contra Costa Canal—Lining cured with white-pigmented compound. Boden 449
—Transit mixers used effectively. Boden . 269
Copeland, R. E.—Nature of portland cement paints and proposed recommended practice for their application to concrete surfaces. Report Com. 616..... 485
—Disc. Observations on the durability of dry tamped silo staves. (Suppl. '42) 252–1
Cores — Pavement — Nonuniformity in compressive strength. Glover..... 133
Coverage to protect reinforcing. (JPP 38-89)..... 360
Cox, Kenneth C.—Tests of reinforced concrete beams with recommendations for attaining balanced design..... 65

Crabbs, Austin—Disc. Good practice in concrete masonry wall construction. (Suppl. '42) 328–1
Crum, Roy W.—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42) 541
Curing compound—made on job. (JPP 38-100) Jones 521

CURING

Canal-lining—Sprayed coats of white-pigmented compound. Boden 449
Emulsion—Made on job. (JPP 38-100) Jones 521
Control of early volume changes. Swayze .. 425

D

Davis, Raymond E.—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42) 236–1
—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.) 36–1
—Concrete of the future. (JPP 38-101) 523
Design diagrams for square concrete columns eccentrically loaded in two directions. Andersen 149
—Disc. Hajnal-Konyi. (June '42 Jl.). 164–1
Determining cement content of hardened concrete. (JPP 38-98) Carlson 477
—reinforcement in hardened concrete. (JPP 38-104) Flodin 527
Dill, R. E.—Some experience with prestressed steel in small concrete units 165
Dolomitic limestone—Low thermal coefficient—cause of failures. Pearson 29

DURABILITY

Disintegration—Dry tamped silo staves. Hughes, Anderson 237
Resistance to freezing and thawing with aluminum admixture. (JPP 38-79) Carlson 184, 274

E

Early concrete volume changes and their control. Swayze 425
Earthquake stresses in frame structures. Glover 453
—Disc. White, Sollid, Glover. (Suppl. '42) 472–1
Eccentric loading of columns—Two directions. Andersen 149
Effect of aluminum powder on durability of concrete. (JPP 38-79) Carlson 184, 274
Effect of belt transportation on concrete aggregate grading. Williams 329
Effect of change in moisture-content of the creep of concrete under a sustained load. Pickett 333
—Disc. Pickett. (Suppl. '42) 356–1
Efflorescence—How to prevent. (JPP 38-83) 275
Emulsion "P. J."—Curing compound. (JPP 38-100) Jones 521

ENGINEERING DESIGN

Beams — Rectangular — Balanced design. Cox 65
Beams—Stresses—Shrinkage. Pickett 333
Bond stress of flat steel. (JPP 38-86) Gilkey 357
Buildings—ACI code requirements. (JPP 38-96) Richart 476
Building codes—National emergency. Bertin 281
—walls—Airplane motor test cells. (JPP 38-94) 474
Columns — Square — Eccentrically loaded. Andersen 149
—Tied. (JPP 38-77) Willson 181
Fibre stress—Limitation. (JPP 38-92) Richart 364
Frame structures—Earthquake stresses. Glover 453
Stirrup spacing—Computing. (JPP 38-99) Goodwin 478
—Formula and diagram. (JPP 38-105) Zbinden 528
Evaluating "n". (JPP 38-103) Talbot, Richart 525
Exposed aggregate—Naval Medical Center. Fischer 289

F

Fabricating and erecting column forms. (JPP 38-81). Macklin 273

FAILURES

Bond bars to resist. (JPP 38-74) Gilkey .. 82
Cast stone—Low thermal coefficient. Pearson 29
Farmer, H. G.—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42) 541
Fischer, Hugo C.—Architectural concrete on the New Naval Medical Center 289
Flodin, H. L.—Determining reinforcement in hardened concrete. (JPP 38-104) 527
Forbrich, Louis R.—Temperature effects near concrete surfaces as affected by heat liberation of cement 53
Foresman, C. H.—Disc. Influence of vibration, consistency and grading of aggregate upon the design of concrete (June '42 Jl.) 28–1
—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613 (June '42 Jl.) 208–1
—Disc. Proposed recommended practice for measuring, mixing, and placing concrete. Report of Com. 614. (June '42 Jl.) 120–1

Formula and a diagram for the spacing of stirrups. (JPP 38-105) Zbinden..... 528

Friberg, Bengt—Disc. Bond stress in concrete pull-out specimens. (June '42 Jl.)..... 52–1

G

Germundsson, Thor—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1

Gilkey, Herbert J.—Bars to resist bond failures. (JPP 38-74)..... 82
—Bond of flat steel reinforcing. (JPP 38-86) 357

Glover, Robert E.—Earthquake stresses in frame structures..... 453
—Disc. (Suppl. '42)..... 472–1

Glover, V. L.—Study of the cause of nonuniformity in the compressive strength of concrete pavement cores..... 133
—Disc. (June '42 Jl.)..... 148–1

Goldbeck, A. T.—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42)..... 541

Good practice in concrete masonry wall construction. Tippy..... 317
—Disc. Anderegg, Wilk, Pearson, Parsons, Crabbs, Tippy. (Suppl. '42)... 328–1

Goodwin, W. C.—Computing stirrup spacing in non-rectangular shear diagrams. (JPP 38-99)..... 478

H

Hajnal-Konyi, K.—Disc. Design diagrams for square concrete columns eccentrically loaded in two directions. 164–1

Horn, A. E.—Disc. Proposed specification for cast stone. Report Com. 704. (Suppl. '42)..... 316–9

Hornibrook, F. B.—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.)... 36–1

How to prevent efflorescence. (JPP 38-83) 275

Hubbard, Fred—"Pops" in slag concrete. (JPP 38-85)..... 278
—Slag aggregate—Wet or dry. (JPP 38-88).. 359

Hughes, C. A. (with Anderson). Observations on the durability of dry tamped silo staves. 237
—Disc. (Suppl. '42)..... 252–1

Hurlburt, R. W.—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613. (June '42 Jl.)..... 208–1

Hutchinson, G. W.—Influence of vibration, consistency, and grading of aggregate upon the design of concrete..... 9
—Disc. (June '42 Jl.)..... 28–1

I

Influence of vibration, consistency, and grading of aggregate upon the design of concrete. Hutchinson.....9
—Disc. Foresman, Weymouth, Hutchinson. (June '42 Jl.)..... 28–1

Inspection—ACI Manual of Concrete Inspection—Report of Com. 611. Kelly.. (Separate publication July 1941)
—Disc. Cohen, Crum, Julian, Thomson, Waugh, Protze with Parks and Ball, Goldbeck, Schnarr, Swayze, Farmer, Kelly. (Suppl. '42.)..... 541

—Compliance with specifications—Water content. Warberg..... 169

Irwin, A. C.—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613. (June '42 Jl.)..... 208–1

J

Johnston, Bruce (with Sutherland)—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1

Jones, Paul A.—Concrete curing compound—made on the job. (JPP 38-100)... 521

Jones, Valens—Disc. Study of the cause of nonuniformity in the compressive strength of concrete pavement cores. (June '42 Jl.)..... 148–1

Julian, O. G.—Disc. ACI Manual of concrete inspection—Report of Com. 611. (Suppl. '42)..... 541

K

Kaiser, W. G.—Reinforcing for concrete masonry walls. (JPP 38-73)..... 81
—Time interval between successive coats of stucco. (JPP 38-80)..... 184

Kalinka, J. E.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1

Kauf, Leo—Disc. Saving steel in reinforced concrete design. (April '42 Jl.) 288–1

Kellam, B.—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.)..... 36–1

Kelly, J.W.—ACI Manual of Concrete Inspection. Report of Com. 611..... (Separate publication July 1941)
—Disc. (Suppl. '42)..... 541
—Simple method of estimating percentage of sand. (JPP 38-76)..... 83

Knight, Lane—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1

L

Larson, Guy H.—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613 (Jan. '42 Jl.) ... 203
(June '42 Jl.) ... 208–1
Laundry tray manufacture. (JPP 38-75) .. 82

LAWS AND PROPERTIES

Bleeding—Causes and control. (JPP 38-93) Powers ... 473
Bond—Deformed bars. (JPP 38-74) Gilkey 82
—Distribution in pull-out specimens. Watstein ... 37
—Effect of aluminum powder. (JPP 38-78) McMillan ... 183
—Flat Steel. (JPP 38-86) Gilkey ... 357
Compressive strength—Nonuniformity of cores. Glover ... 133
Consistency—Influence on design. Hutchinson ... 9
Cracking—Effect of heat liberation Forbrich ... 53
Creep—Effect of sustained load. Pickett ... 333
Durability—effect of aluminum powder. (JPP 38-79) Carlson ... 184, 274
Efflorescence—How to prevent. (JPP 38-83) 275
Expansion—Reaction between cement and aggregate. Stanton, Porter, Meder, Nicol .. 209
Flexural stress—Limitation on extreme fibre. (JPP 38-92) Richart ... 364
Heat liberation—Effect near surface. Forbrich ... 53
Modulus of elasticity "n". (JPP 38-103) Talbot, Richart ... 524
Performance—Long-time study. McMillan 441
Plastic flow—Effect of sustained load. Pickett ... 333
Quality—Future expectation. (JPP 38-101) Davis ... 523
Shrinkage. (JPP 38-91) Carlson ... 363
Volume changes—control of. Swayze ... 425

M

Machine methods for trimming subgrade and placing concrete canal lining. Boden ... 177
Macklin, Charles—Fabricating and erecting column forms. (JPP 38-81) ... 273
Manual of Concrete Inspection—Report of Com. 611 J. W. Kelly, Author-Chairman ... (Separate publication July 1941)
—Disc. Cohen, Crum, Julian, Thomson, Waugh, Protze with Parks and Ball, Goldbeck, Schnarr, Swayze, Farmer, Kelly. (Suppl. '42) ... 541

MASONRY UNITS

Cast stone — Specifications — proposed. Walker ... 313
Preshrinkage of—Wall construction. Tippy. 317
Shrinkage in walls—Reinforcement. (JPP 38-73) Kaiser ... 81
Silo staves—Dry tamped. Hughes, Anderson ... 237
Aggregates—Dolomitic—Low thermal coefficient—cause of failure. Pearson ... 29

MATERIALS AND TESTS

—Expansion due to alkali reaction. Stanton, Porter, Meder, Nicol ... 209
—Exposed—Surface finish—New Medical Center. Fischer ... 289
—Grading—Effect of belt transportation. Williams ... 329
—Grading—Effect on design. Hutchinson. 9
—Lightweight—waylite. Washa and Wendt. 505
—Sand—Estimating percentage of sand. (JPP 38-76) Kelly ... 83
—Slag—"Pops" (JPP 38-85) Hubbard ... 278
—Slag—Wet or dry. (JPP 38-88) Hubbard 359
Aluminum powder—Effect on bond. (JPP 38-78) McMillan ... 183
—Effect on durability of concrete. (JPP 38-79) Carlson ... 184, 274
Cement—alkali content—Effect of. Stanton, Porter, Meder, Nicol ... 209
Curing compounds — white-pigmented — canal lining. Boden ... 449
Form lining—Absorptive. Vidal, Blanks ... 253
Hydrated lime—Constituent in paint. Copeland ... 485
Paint—Portland cement base. Tippy ... 317
—portland cement base—application. Com. 616 report. Copeland ... 485
Portland cement—constituent in paint. Com. 616 report. Copeland ... 485
—Performance—Long-time study. McMillan ... 441
Steel—Bond stress—Deformed bars. Watstein ... 37
McMillan, F. R.—Aluminum powder to increase bond of concrete to reinforcing steel. (JPP 38-78) ... 183
—Progress in the long-time study of cement performance in concrete ... 441
Measuring, mixing and placing concrete. Com. 614 Report. Tuthill ... 93
Meder, L. C. (with Stanton, Porter and Nichol)—California experience with the expansion of concrete through reaction between cement and aggregate ... 209
Meissner, Harmon S.—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42). 236–1
—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.) ... 36–1
Metal supports for reinforcement—Proposed recommended practice. Report Com. 319. Zabriskie ... 173
Miller, Dalton G.—Disc. Observations on the durability of dry tamped silo staves. (Suppl. '42) ... 252–1

MIXTURES
Air content—Measuring. Pigman..... 121
Design—Details. (JPP 38-84) Collins.... 276
—Influence of vibration consistency and grading. Hutchinson..... 9
—Lightweight concrete. Washa and Wendt. 505
—Percentage of sand—Estimating. (JPP 38-76) Kelly..... 83
Proportions—Determination in hardened concrete. (JPP 38-98) Carlson..... 477
—Proposed recommended practice—Committee 613 report. Blanks, Chairman; Vidal, Secy..... 193
Moreell, Ben—President's address..... 421
Morris, Clyde T.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Mortar—For concrete masonry. Tippy... 317
Mud jacks—strengthening concrete pavement. (JPP 38-95) Poulter..... 475

N

"n"—Evaluating modulus of elasticity. (JPP 38-103) Talbot, Richart..... 525
Nature of portland cement paints and proposed recommended practice for their application to concrete surfaces. Report Com. 616. Copeland..... 485
Naval Medical Center—Exposed aggregate finish. Fischer..... 289
Nelles, John S.—Disc. Properties of Lightweight Structural Concrete made with waylite aggregate. (Suppl. '42)..... 520–1
Nicol, Allen (with Stanton, Porter and Meder) California experience with the expansion of concrete through reaction between cement and aggregate..... 209

O

Observations on the durability of dry tamped silo staves. Hughes, Anderson... 237
—Disc. Copeland, Miller, Hughes. (Suppl. '42)..... 252–1

P

Paints—portland cement base—application—Com. 616 report. Copeland..... 485
Papers for American Concrete Institute—How to prepare...... 1
Parks, Frederick B. (with Ball and Protze J.)—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42). 541
Parsons, Douglas—Disc. Good practice in concrete masonry wall construction. (Suppl. '42)..... 328–1

PAVEMENT
Cores—Compressive strength—Nonuniformity. Glover..... 133
Highway — Military — Strengthening with mud jacks. (JPP 38-95) Poulter..... 475
Peabody, Dean, Jr.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Pearson, J. C.—Concrete failure attributed to aggregate of low thermal coefficient..... 29
—Disc. (June '42 Jl.)..... 36–1
—Disc. Good practice in concrete masonry wall construction. (Suppl. '42)..... 328–1
Pickett, Gerald—Effect of change in moisture-content of the creep of concrete under a sustained load..... 333
Pigman, Geroge L.—Vacuum method of measuring the air content of fresh concrete. 121
Placing cold concrete in hot weather. (JPP 38-102) Carlson..... 524
"Pops" in slag concrete. (JPP 38-85) Hubbard..... 278
Porter, O. J. (with Stanton, Meder and Nichol)—California experience with the expansion of concrete through reaction between cement and aggregate..... 209
Post, Chester L.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Poulter, John W.—Use of mud jack in strengthening concrete pavement. (JPP 38-95)..... 475
Powers, T. C.—Causes and control of bleeding. (JPP 38-93)..... 473
—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613. (Jan. '42 Jl.).... 202
(June '42 Jl.)..... 208–1
Practical specifications for structural concrete. (JPP 38-90) Tuthill..... 362

PRECAST UNITS
Wall panels — Exposed aggregate — New Medical Center. Fischer..... 289
Preshrinkage of masonry units. Tippy... 317
President's Address. Moreell..... 421
Prestressed steel—Small units—Posts—Slabs. Dill..... 165
Price, W. H.—Disc. Proposed recommended practiee for the design of concrete mixes. Report Com 613. (Jan. '42 Jl.)..... 204
Proctor, Carlton S.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Progress in the long-time study of cement performance in concrete. McMillan.... 441
Properties of lightweight structural concrete made with waylite aggregate. Washa and Wendt..... 505
—Disc. Nelles, Washa and Wendt (Suppl. '42)..... 520–1
Proposed recommended practice for the design of concrete mixes. Report Com. 613. Blanks, Vidal..... 193

—Disc. Powers, Larson, Price. (Jan. '42 Jl.) 202, 203, 204
—Disc. Conv. Blanks, Powers, Larson, Britzius, Hurlburt, Irwin; since the conv. Witt, Foresman, Ruettgers. (June '42 Jl.) 208–1
Note—for measuring, mixing, and placing concrete. Report of Com. 614, Tuthill. 93
—Disc. Conv. Tuthill, Foresman, Tuthill. (June '42 Jl.) 120–1
—for use of metal supports for reinforcement. Report Com. 319. Zabriskie..... 173
Proposed specification for cast stone—Report Committee 704. Walker..... 313
—Disc. Conv. Walker. (June '42 Jl.). 316–1
—Disc. Tucker, Horn, Walker. (Suppl. '42) 316–9
Protze, Herman G. Jr. (with Parks, and Ball)—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42) 541
Publications policy of ACI 1

R

Reagel, F. V. (with Willis)—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.) 36–1
Reinforcement—Determination of. (JPP 38-104) Flodin..... 527
Reinforcing for concrete masonry walls. (JPP 38-73) Kaiser..... 81
—12-in. walls of airplane motor test building. (JPP 38-94)..... 474
Research man's troubles. (JPP 38-82).... 275

RESEARCH

Portland cement behavior. (JPP 38-82)... 275
Rhoades, Roger—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42)..... 236–1
Richart, F. E.—The ACI Code's test load requirement. (JPP 38-96)..... 476
—Evaluating "n". (JPP 38-103)..... 525
—Disc. Saving Steel in reinforced concrete design. (April '42 Jl.)..... 288–1
—Why the limitation on extreme fiber stress. (JPP 38-92)..... 364
Ruettgers, Arthur—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613. (June '42 Jl.)..... 208–1

S

Saving steel in reinforced concrete design. Bertin..... 281
—Disc. Conv.: Richart, Whitney, Peabody, Schorer, Germundsson, Kalinka, Withey, Kauf, Strehan, Post, Spiker, Sutherland, and Johnson, Proctor, Knight; since conv.: Morris. (April '42 Jl.)..... 288–1
—Disc. Allbright, Bertin. (Suppl. '42).288–37
Schnarr, Wilfrid—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42)..... 541
Scholer, Charles H.—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42). 236–1
Schorer, Herman—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Shrinkage of concrete. (JPP 38-91) Carlson..... 363
Silo staves — dry tamped — Durability. Hughes, Anderson..... 237
Simple method of estimating percentage of sand. (JPP 38-76) Kelly..... 83
Slag aggregate—Wet or dry. (JPP 38-88) Hubbard..... 359
Slag concrete—"Pops." (JPP 38-85) Hubbard..... 278
Sollid, Erik — Disc. Earthquake stresses in frame structures. (Suppl. '42)..... 472–1
Some details in designing and mixing concrete. (JPP 38-84) Collins..... 276
Some experience with prestressed steel in small concrete units. Dill..... 165

SPECIFICATIONS

Cast stone—Committee 704 report. Walker 313
Structural concrete—Practical. (JPP 38-90) Tuthill..... 362
Water content of concrete. Warberg..... 169
Spiker, W. C.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Stanton, Thomas E. (with Porter, Meder and Nichol)—California experience with the expansion of concrete through reaction between cement and aggregate..... 209
—Disc. (Suppl. '42)..... 236–1
Stirrup spacing—Computing—Non-rectangular shear diagrams. (JPP 38-99) Goodwin..... 478
—spacing—formula and diagram for. (JPP 38-105) Zbinden..... 528
Strehan, Geo. S.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Stress-creep relationship—sustained load. Pickett..... 333

STRUCTURAL MEMBERS

Columns—Square eccentrically loaded. Andersen..... 149
Stucco—time interval between coats. (JPP 38-80) Kaiser..... 184
Study of the cause of nonuniformity in the compressive strength of concrete pavement cores. Glover..... 133
—Disc. Jones, Wing, and Glover. (June '42 Jl.)..... 148–1

Sutherland, Hale (with Johnston.)—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Swayze, M. A.——Early concrete volume changes and their control..... 425
—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42)... 541
—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.)..... 36–1

T

Talbot, A. N.—Evaluating "n". (JPP 38-103)..... 525
Temperature effects near concrete surfaces as affected by heat liberation of cement. Forbrich..... 53
TESTS OF MEMBERS AND COMPLETED STRUCTURES
Beams—Rectangular—balanced design. Cox 65
Buildings—ACI code requirements. (JPP 38-96) Richart..... 476
Posts—slabs—Prestressed steel in small units. Dill..... 165
Pull-out specimens—Bond stress. Watstein 37
Tests of reinforced concrete beams with recommendations for attaining balanced design. Cox..... 65
—Disc. Whitney and Abeles. (June '42 Jl.)..... 80–1
Thermal changes—Heat liberation—Effect of. Forbrich..... 53
—coefficient of aggregate—cause of failures. Pearson..... 29
Thompson, J. P.—Adopting the ACI code by reference. (JPP 38-97)..... 477
Thomson, H. F.—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42)..... 541
Tied column formulas. (JPP 38-77) Willson..... 181
Time interval between successive coats of stucco. (JPP 38-80) Kaiser..... 184
Tippy, Kenneth C.—Good practice in concrete masonry wall construction..... 317
—Disc. (Suppl. '42)..... 328–1
Transit Mixers used effectively on the Contra Costa Canal. Boden..... 269
Tucker, John, Jr.—Disc. Proposed specification for cast stone. Report Committee 704. (Suppl. '42)..... 316–9
Tuthill, Lewis H.—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42)..... 236–1
—Practical specifications for structural concrete. (JPP 38-90)..... 362
—Proposed recommended practice for measuring, mixing, and placing concrete. Report of Com. 614..... 93
—Disc. Conv. Foresman, Tuthill. June '42 Jl.)..... 120–1

U

Use of mud jack in strengthening concrete pavement. (JPP 38-95) Poulter... 475

V

Vacuum method of measuring the air content of fresh concrete. Pigman..... 121
Vidal, E. N. (with Blanks)—Absorptive form lining..... 253
—Secy., (with Blanks, Ch.)—Proposed recommended practice for the design of concrete mixes. Report Com. 613..... 193
Vibration—Earthquake stresses in frame structures. Glover..... 453
VIBRATION
Vibration—Influence on design of concrete. Hutchinson..... 9

W

Walker, C. G.—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.)..... 36–1
—Proposed specification for cast stone. Report Committee 704..... 313
—Disc. (June '42 Jl.)..... 316–1
—Disc. (Suppl. '42)..... 316–9
Wqrberg, F. J.—Concrete specifications and water content of concrete..... 169
Washa, George W. (with Wendt)—Properties of lightweight structural concrete made with waylite aggregate..... 505
—Disc. (Suppl. '42)..... 520–1
Watstein, David—Bond stress in concrete pull-out specimens..... 37
Waugh, W. R.—Disc. ACI Manual of Concrete Inspection—Report of Com. 611. (Suppl. '42)..... 541
Waylite aggregate—properties of. Washa and Wendt..... 505
Wendt, Kurt F. (with Washa)—Properties of lightweight structural concrete made with waylite aggregate..... 505
—Disc. (Suppl. '42)..... 520–1
Weymouth, C. A. G.—Disc. Influence of vibration, consistency and grading of aggregate upon the design of concrete. (June '42 Jl.)..... 28–1
What concrete coverage to protect reinforcing. (JPP 38-89)..... 360
White, Merit P.—Disc. Earthquake stresses in frame structures. (Suppl. '42)..... 472–1
Whitney, Chas. S.—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
—Disc. Tests of reinforced concrete beams with recommendations for attaining balanced design. (June '42 Jl.)..... 80–1

Why the limitation on extreme fiber stress. (JPP 38-92) Richart..... 364
Wilk, Benjamin—Disc. Good practice in concrete masonry wall construction. (Suppl. '42)..... 328–1
Williams, Gordon L.—Effect of belt transportation on concrete aggregate grading.... 329
Willis, T. F. (with Reagel)—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.)..... 36–1
Willson, C. A.—Comparison of reinforced concrete tied column formulas. (JPP 38-77) 181
Wing, S. P.—Disc. Study of the cause of nonuniformity in the compressive strength of concrete pavement cores. (June '42 Jl.)..... 148–1
Withey, M. O.—Disc. Concrete failure attributed to aggregate of low thermal coefficient. (June '42 Jl.)... 36–1
—Disc. Saving steel in reinforced concrete design. (April '42 Jl.)..... 288–1
Witt, J. C.—Disc. California experience with the expansion of concrete through reaction between cement and aggregate. (Suppl. '42)..... 236–1
—Disc. Proposed recommended practice for the design of concrete mixes. Report Com. 613. (June '42 Jl.).... 208–1

X

X-ray—Determining reinforcement in hardened concrete. (JPP 38-104) Flodin 527

Y

Young, R. B.—Disc. Concrete failure attributed to aggregate of low thermal coefficient (June '42 Jl.)..... 36–1

Z

Zabriskie, William F.—Proposed recommended practice for use of metal supports for reinforcement. Report of Com. 319.... 173
Zbinden, E.—A formula and a diagram for the spacing of stirrups. (JPP 38-105)..... 528

INDEX

Current Reviews

From Journal of the American Concrete Institute, Vol. 13, Sept. 1941 to June 1942

For information as to indexing methods see Proceedings *Index, p. 581*

A

Absorptive form lining—Tests at Friant. (Review) *Engineering News-Record* 536
Air raids—Damage to buildings. (Review) Rep. Science Com., I. S. E. 189
—protection. (Review) *Engineering News-Record* 533
Alkalies—In cements—Rapid determination. (Review) Glaze. *Rock Products* 86
—Removal in portland cement manufacture. (Review) Woods. *Rock Products* 483
American highway practice, Volume 1. (Review) Hewes. John Wiley & Sons, Inc. 482
Aqueduct—Grouting tunnel lining. (Review) *Engineering News-Record* 534

ARCHITECTURAL DESIGN

Bomb shelters. (Review) Krause. *Zement* 85
Ceilings—Steel floor slab forms. (Review) *Engineering News-Record* 86
Surface finish.—Precast wall facing. (Review) Fischer. *Engineering News Record* 366
Surfaces—Forming details. (Review) Boase. *Engineering News-Record* 187
Artificial stone cornices. (Review) *Beton-Stein Zeitung* 366
Asbestos-cement tubes—Roof construction. (Review) *Concrete Building and Concrete Products* 482

B

Beehive for munitions storage. (Review) MacLeay. *Engineering News-Record* 535
Belt conveyor—Dry dock construction. (Review) *Engineering News-Record* 366
Bomb-proof protection—Factors in. (Review) Wessman, Rose. *Engineering News-Record*. 186
—structures. (Review) Krause. *Zement* 85
Bomb tests of materials and structures. (Review) *Engineering News-Record* 538

BREAKWATERS—DOCKS AND SEA WALLS

Drydock—Underwater construction. (Review) *Engineering News-Record* 535
Navy graving dock—Off shore—Construction in the dry. (Review) Seibert. *Engineering News-Record* 534

BRIDGE

North Avenue, Chicago—Design. (Review) Smith, Lillard. *Proc. Amer. Soc. C. E.* 188
Buildings damaged by air raids and notes relative to reconstruction. (Review) *Report of Science Com. I. S. E.* 189

BUILDINGS

Framed—Repair of air raid damage. (Review) *Report Science Com., I. S. E.* 189
Rigid frame. (Review) *Engineering News-Record* 186
Warehouse—Designed to speed construction. (Review) *Engineering News-Record* 538
War-time—Three pin portal frames. (Review) *Concrete and Constructional Engineering* 367

C

Cantilever forms. (Review) Cox. *Engineering News-Record* 366
—preferred at Mahoning. (Review) Cox. *Engineering News-Record* 366
—for Shasta Dam. (Review) *Engineering News-Record* 85
Cellular bridge structure. (Review) Panhorst. *Engineering News-Record* 85
Cement dispersion and concrete quality. (Review) Scripture. *Engineering News-Record* 367
Concrete beehive for munitions storage. (Review) MacLeay. *Engineering News-Record* 535
—core wall at Merriman Dam. (Review) *Engineering News-Record* 185
—flower and plant pots. (Review) Baumgarten. *Concrete Building & Concrete Products* 533
—in sea-water. (Review) Hadley. *A Revised Viewpoint Needed. Trans. Am. Soc. C. E.* .. 538
Concrete rockers for Hawaiian bridges. (Review) Brinker. *Engineering News-Record* .. 533
Conduit—Enclosed river under highway. (Review) *Engineering News-Record* 534
Conservation of critical materials approved by executive committee of AASHO. (Review) *The Constructor* 483
—of critical materials. General Construction. (Review) *The Constructor* 483
Continuous rectangular slabs—Rigid supports. (Review) Maugh, Pan. *Proc. Am. Soc. C. E.* 187
Corrosive effect of inorganic fertilizers on concrete. (Review) Pillsbury. *Civil Engineering* 90
Crack prevention—Hiwassee dam. (Review) Laurgaard. *Proc. Amer. Soc. C. E.* 187

CONSTRUCTION—DETAILS, METHODS AND COSTS

Bridge—Arch—Falsework set on drum gates. (Review) *Engineering News-Record* 534

Bridge piers—Welded reinforcing—Pit River bridge. (Review) *Engineering News-Record* 86
Buildings—Cement plant—Sliding scaffolds. (Review) *Engineering News-Record* 536
Buildings—Precast portal frames. (Review) *Concrete and Constructional Engineering* ... 367
—Reconstruction—Air raid damage. (Review) *Report Sciencd Com., I. S. E.* 189
Conduit—Twin section supporting highway—special arch forms. (Review) *Engineering News-Record* 534
Dam—Cantilever forms. (Review) *Engineering News-Record* 85
—Crack prevention. (Review) Laurgaard. *Proc. Am. Soc. C. E.* 187
—Grand Coulee. (Review) *Engineering News-Record* 185
—Merriman—Core Wall. (Review) *Engineering News-Record* 185
Dock—Off shore—In dry. (Review) Seibert. *Engineering News-Record* 534
Drydock—Placing by belt conveyor. (Review) *Engineering News-Record* 366
—Underwater operations—Tremie-concrete. (Review) *Engineering News-Record* 535
Floor slabs—Pan forms. (Review) *Engineering News-Record* 86
Floors—White cement finish. (Review) *Engineering News-Record* 535
Forms—Absorptive lining. (Review) *Engineering News-Record* 536
—Cantilever. (Review) Cox. *Engineering News-Record* 366
—For architectural concrete. (Review) Boase. *Engineering News-Record* 187
—Sliding—Pit walls. (Review) *Engineering News-Record* 186
Hangars—Navy structures. (Review) *Engineering News-Record* 366
Highway—American practice. (Review) Hewes. *John Wiley & Sons* 482
Munitions storage—Beehive. (Review) MacLeay. *Engineering News-Record* 535
Pavement—Airbase Runways. (Review) *Engineering News-Record* 534
—Blocks—Early projects. (Review) Bartholomew. *Engineering News-Record* 186
—Street—Simplified construction. (Review) *Engineering News-Record* 533
Post-war plans. (Review) *Concrete Building & Concrete Products* 89
Roof—Asbestos-cement tubes. (Review) *Concrete Building and Concrete Products* .. 482
Seawall—Water front development at Corpus Christi. (Review) *Engineering News-Record* 185
Tanks—Thinshell—Prestressed bands. (Review) *Engineering News-Record* 536
Tunnel lining—Grouting. (Review) *Engineering News-Record* 534
—World's longest. (Review) *Engineering News-Record* 365
Walls—Placing—Pneumatic shotcrete. (Review) Greene. *Engineering News-Record* 185
Warehouse—Designed for rapid erection. (Review) *Engineering News-Record* 538
—Precast framing units. (Review) *Engineering News-Record* 537

CURING

Steam—For light weight products (Review) *Beton-Stein Zeitung* 367

D

DAMS

Grand Coulee—Nears completion. (Review) *Engineering News-Record* 185
Hiwassee—Crack prevention. (Review) Laurgaard. *Proc. Am. Soc. C. E.* 187
Merriman—Core wall. (Review) *Engineering News-Record* 185
Shasta dam—Cantilever forms. (Review) *Engineering News-Record* 85
Design and construction of tower silos. (Review) Pennington. *Concrete Building & Concrete Products* 481
Designing reinforced-concrete beams with variable moments of inertia. (Review) Ellis. *Engineering News-Record* 365
Determining the heat evolution of cement. (Review) Takata. *Cement* 537
—the surface area by air permeability method. (Review) Meyers. *Rock Products* 482
Development of bomb-proof structures. (Review) Krause. *Zement* 85
Dispersion—Effect on quality. (Review) Scripture. *Engineering News-Record* 367
Dolomites—Resistance to freezing and thawing. (Review) Willman. *Rock Products* .. 481
Drydock concreting by belt conveyor. (Review) *Engineering News-Record* 366
Dry process vs. wet process in portland cement manufacture (Review) *Cement and Lime Manufacture* 482
Drydock—Underwater construction. (Review) *Engineering News-Record* 535

DURABILITY

Disintegration—Effect of nitrogen. (Review) Pillsbury. *Civil Engineering* 90
—Effect of treated cement. (Review) Swayze. *Engineering News-Record* 87

E

Effect of admixtures on portland cement. (Review) Jumper and Kalousek. *Rock Products* 535
—of deflection of the supporting beams on the bending moments in a uniformly loaded slab. (Review) Burns. *The Journal of the Institution of Engineers Australia* 368

ENGINEERING DESIGN

Beams—Bending moments—Uniform loading. (Review) Burns. *The Journal of the Institution of Engineers, Australia* 368
—Variable moments of inertia. (Review) Ellis. *Engineering News-Record* 365

Bridge—Cellular structure. (Review) Panhorst. *Engineering News-Record*..... 85
—2-hinged rigid frame—Extensometer measurements. (Review) Smith, Lillard. *Proc. Amer. Soc. C. E.*..... 188
—rockers—Hawaiian. (Review) Brinker. *Engineering News-Record*..... 533
Buildings—Bomb-proof. (Review) Wessman, Rose. *Engineering News-Record*.... 186
—Rigid frame. (Review) *Engineering News-Record*..... 186
Critical materials of construction. (Review) *The Constructor*..... 483
Floor—Grid system. (Review) Szego. *Engineering News-Record*..... 536
Hangars—Two-hinged arch ribs. (Review) *Engineering News-Record*..... 366
Highway—American practice. (Review) Hewes. *John Wiley & Sons*..... 482
—Trends. (Review) Anderson. *Engineering News-Record*..... 533
Plates—Concentrated loading. (Review) Westergaard. *Proc. Am. Soc. C. E.*..... 539
Prestressed structures. (Review) Puston. *Beton und Eisen*..... 91
Rectangular sections — Minimum steel graphs. (Review) Massarik. *Conc. & Constr. Eng.*..... 365
Silos—Tower. (Review) Pennington. *Concrete Building & Concrete Products*..... 481
Slabs—Concentrated loading. (Review) Westergaard. *Proc. Amer. Soc. C. E.*.... 539
—Continuous rectangle—Rigid supports. (Review) Maugh, Pan. *Proc. Am. Soc. C. E.*..... 187
Tanks—Gasoline storage—Under water. (Review) Hagerman, Host, Granholn. *Teknisk Tidskrift*..... 91
Walls—Shrinkage reinforcement. (Review) Ropp. *Engineering News-Record*..... 86
Experiments on the reduction of crack formation in road concrete. (Review) Schonberg. *Betonstrasse*..... 539
Extensometer measurements—2-hinge rigid frame. (Review) Smith, Lillard. *Proc. Amer. Soc. C. E.*..... 188
—North Avenue bridge, Chicago, Ill. (Review) Smith and Lillard. *Proc. Amer. Soc. C. E.*..... 188

F

Factors in aerial bombardment protection. (Review) Wessman and Rose. *Engineering News-Record*..... 186
Falsework for arch bridge—On drum gates. (Review) *Engineering News-Record*..... 534
—for arches set on drum gates. (Review) *Engineering News-Record*..... 534
Fineness—Air permeability method of determination. (Review) Meyers. *Rock Products*..... 482
First concrete paving 50 years old. (Review) Bartholomew. *Engineering News-Record*.8.. 186
Forming details and practices for architectural concrete. (Review) Boase. *Engineering News-Record*..... 187
Forms—Cantilever—Shasta Dam. (Review) *Engineering News-Record*..... 85
Flower pots—Manufacture in England. (Review) Baumgarten. *Concrete Building & Concrete Products*..... 533

G

Garnet-hydrogarnet—Sulfate resistance. (Review) Flint, Wells. *Journal of Research of the National Bureau of Standards*..... 86
Gasoline storage tanks of concrete. (Review) *Teknisk Tidskrift*..... 91
—Under water. (Review) Hagerman, Host, Granholm. *Teknisk Tidskrift*..... 91
Glass in portland cement clinker. (Review) Tavasci. *Zement*..... 87
—in portland cement. (Review) Tavasci *Zement*..... 87
Grand Coulee Dam nears completion. (Review) *Engineering News-Record*..... 185
Graving dock—Built in dry. (Review) Seibert. *Engineering News-Record*..... 534
Grid system floor—Long spans. (Review) Szego. *Engineering News-Record*..... 536
—of record spans. (Review) Szego. *Engineering News-Record*..... 536
Grouting aqueduct tunnel lining. (Review) *Engineering News-Record*..... 534
—tunnel lining on the aqueduct. (Review) *Engineering News-Record*..... 534

H

Hangars—Navy structures at San Diego. (Review) *Engineering News-Record*..... 366
Heat evolution of cement. (Review) Takata. *Cement*..... 537
How a cellular concrete bridge acts under traffic. (Review) Panhorst. *Engineering News-Record*..... 85

I

Influence of steel upon strength and deflections of reinforced concrete beams. (Review) Suenson. *Ingen. Skrifter*..... 188
Inorganic fertilizers—Corrosive effect of. (Review) Pillsbury. *Civil Engineering*..... 90
Investigation of special cements in the laboratory and in roads. (Review) Graf and Walz. *Zement*..... 88

L

LAWS AND PROPERTIES

Corrosion—Effect of nitrogen. (Review) Pillsbury. *Civil Engineering*..... 90
Fatigue—Repeated stresses. (Review) Lea. *Struct. Engr.*..... 88
Durability—Treated cement. (Review) Swayze. *Engineering-News-Record*..... 87

Resistance to sea-water. (Review) Hadley. *Trans. Am. Soc. C. E.* ... 538
Shrinkage—Road slabs—Preventative methods. (Review) Schonberg. *Betonstrasse.* 539
Strength—Fineness—New Reich districts. (Review) Eitel. *Zement* ... 85
Sulfate resistance. (Review) *Technical News Bulletin of the National Bureau of Standards* ... 367
Lining the world's longest tunnel. (Review) *Engineering News-Record* ... 365

M

MASONRY UNITS

Lightweight—Curing with steam. (Review) *Beton-Stein Zeitung* ... 367
Materials testing. (Review) Gilkey, Murphy, & Bergman. *McGraw-Hill Book Co. Inc.* ... 369
Materials testing—Theory and practice. (Review) Gilkey, Murphy, Bergman. *McGraw-Hill Book Co., Inc.* ... 369

MATERIALS AND TESTS

Admixtures—Effect on portland cement. (Review) Jumper, Kalousek. *Rock Products* ... 535
Admixtures—Powdered stone. (Review) Weber. *Betonstrasse* ... 369
Aggregate—Dolomite—Resistance to freezing and thawing. (Review) Willman. *Rock Products* ... 481
—Powdered stone—Road construction. (Review) *Betonstrasse* ... 369
Cements—Alkali determination. (Review) Glaze, *Rock Products* ... 86
Cement—Fineness determination—Permenability method. (Review) Meyers. *Rock Products* ... 482
—Heat evolution. (Review) Takata. *Cement* ... 537
—New Reich districts in East—Fineness data. (Review) Eitel. *Zement* ... 85
—Research, 1940. (Review) Platzmann. *Zement* ... 185
—Special—Laboratory investigations. (Review) Graf, Walz. *Zement* ... 88
—Substitute—To conserve coal. (Review) Bergstrom. *Teknisk Tidskrift* ... 89
—Thermal studies. (Review) Eitel. *Zement* ... 85
—Treated—Use in highway construction. (Review) Anderson. *Engineering News-Record* ... 533
Dispersing agents—Effect on quality. (Review). Scripture. *Engineering News-Record* ... 367
Engineering materials. (Review) Gilkey, Murphy, Bergman. *McGraw-Hill Book* .. 369
Portland cement—Effect of admixtures. (Review) Jumper, Kalousek. *Rock Products* ... 535
—Manufacture—Clinker—Glass in. (Review) Tavasci, *Zement* ... 87
—Manufacture—Dry and wet processes compared. (Review) *Cement & Lime Manufacture* ... 482
—Raw mixtures—Treatment for volatilization of alkalis. (Review) Woods. *Rock Products* ... 483
—Sulfate resistance. (Review) *Technical News Bulletin of the National Bureau of Standards* ... 367
—Sulfate resistance—Relationship of garnet-hydrogarnet. (Review) Flint and Wells. *Journal of Research of the National Bureau of Standards* ... 86
Steel—Influence of grade on strength and deflection. (Review) Suenson. *Ingen. Skrifter* ... 188
Minimum-steel graphs for bending and compression. (Review) Massarik. *Concrete and Constructional Engineering* ... 365

MIXTURES

Analysis of hydrated cement structure. (Review) Tavasci. *Zement* ... 87
Proportioning—History of theory. (Review) Andrews. *J. Inst. Eng. Aust.* ... 365
—Unit layer method. (Review) Witt. *Rock Products* ... 481
Moments of inertia—Variable—Design of beams. (Review) Ellis. *Engineering News-Record* ... 365
—in continuous rectangular slabs on rigid supports. (Review) Maugh and Pan. *Proc. Am. Soc. C. E.* ... 187
More durable concrete with treated cement. (Review) Swayze. *Engineering News-Record* ... 87

N

New approach to the problem of concrete wall reinforcing. (Review) Ropp. *Engineering News Record* ... 86
Navy builds concrete hangars at San Diego. (Review) *Engineering News-Record* ... 366
—drydocks make construction history. (Review) *Engineering News-Record* ... 535
—graving dock built off shore in the dry. (Review) Seibert. *Engineering News-Record* .. 534

P

PAVEMENT

Airbase—Construction methods. (Review) *Engineering News-Record* ... 534
First—Square blocks. (Review) Bartholomew. *Engineering News-Record* ... 186
Highway—American design practice. (Review) Hewes. *John Wiley & Sons* ... 482
Road slabs—Reduction of crack formation. (Review) Schonberg. *Betonstrasse* ... 539
Street—Simplifying construction. (Review) *Engineering News-Record* ... 533
Paving methods at an eastern airbase. (Review) *Engineering News-Record* ... 534
Place coefficients—Stress concentrations in plates and slabs. (Review) Westergaard .. 539

Placing and welding reinforcing steel in Pit River bridge piers. (Review) *Engineering News-Record* ... 86
Pneumatically placed concrete for walls of industrial plants. (Review) Greene. *Engineering News-Record* ... 185
Practice of prestressed concrete. (Review) Puston. *Beton und Eisen* ... 91
Post-war reconstruction. (Review) *Concrete Building & Concrete Products* ... 89
Precast concrete framing units for navy warehouse. (Review) *Engineering News-Record* 537
—water storage tanks. (Review). Anon. *Concrete Building & Concrete Products* ... 537
—facing used on Navy hospital. (Review) Fischer. *Engineering News-Record* ... 366

PRECAST UNITS

Building frames—Navy warehouse. (Review) *Engineering News-Record* ... 537
Cornices—Artificial stone. (Review) *Beton-Stein Zeitung* ... 366
Portal frames—Wartime buildings. (Review *Concrete and Constructional Engineering* ... 367
Tank staves—Water storage. (Review) *Concrete Building & Concrete Products* ... 537
Wall facing—Navy hospital. (Review) Fischer. *Engineering News-Record* ... 366
Prestressed concrete. (Review) Puston, *Beton und Eisen* ... 91
—concrete water tanks. (Review) *Engineering News-Record* ... 536
Progress in cement research 1940. (Review) Platzmann. *Zement* ... 185
Properties of the cements from new Reich districts in the East. (Review) Eitel. *Zement* 85
Proportioning of concrete. (Review) Andrews *J. Inst. Eng. Aust.* ... 365
—concrete materials by the unit layer method. (Review) Witt. *Rock Products* ... 481
—Summary of history of theory. (Review) Andrews. *J. Inst. Eng. Aust.* ... 365
Putting a river underground. (Review) *Engineering News-Record* ... 534

R

Rapid method of determining alkalies in cement. (Review) Glaze. *Rock Products*.. 86
Reconstruction after the war. (Review) *Concrete Building and Concrete Products* ... 89
Relationship of the garnet-hydrogarnet series to the sulfate resistance of portland cements. (Review) Flint and Wells. *Journal of Research of the National Bureau of Standards* 86
Removing alkalis by heating with admixtures (Review) Woods. *Rock Products* ... 483
Repeated stresses on reinforced concrete. (Review) Lea. *Struct. Eng.* ... 88

RESEARCH

Cement—Progress in 1940. (Review) Platzmann. *Zement* ... 185
Hydrated cement. (Review) Tavasci. *Zement* ... 87

RESERVOIRS AND TANKS

Gasoline storage—Under water. (Review) Hagerman, Host Granholm. *Teknisk Tidskrift* ... 91
Silos—Construction. (Review) Pennington. *Concrete Building & Concrete Products* ... 481
Swimming pool—Built in a lake. (Review) *Engineering News-Record* ... 187
Water storage—Precast. (Review) *Concrete Building & Concrete Products* ... 537
Water tanks—Prestressed bands around shell. (Review) *Engineering News-Record* 536
Resistance of the Chicago area dolomites to freezing and thawing. (Review) Willman. *Rock Products* ... 481
Rockers for Hawaiian bridges. (Review) Brinker. *Engineering News-Record* ... 533

S

Seawall and waterfront development completed at Corpus Christi. (Review) *Engineering News-Record* ... 185
—Waterfront development at Corpus Christi. (Review) *Engineering News-Record* ... 185
Sea-water—Effect on concrete. (Review) Hadley. *Trans. Am. Soc. C. E.* ... 538
Shasta dam—Construction—Cantilever forms. (Review) *Engineering News-Record* ... 85
Shotcrete—Pneumatically placed walls. (Review) Greene. *Engineering News-Record*.. 185
Shrinkage reinforcement—Walls. (Review) Ropp. *Engineering News-Record* ... 86
Simplifying concrete street construction. (Review) *Engineering News-Record* ... 533
Sixteen stories of concrete—six of steel. (Review) *Engineering News-Record* ... 186
Sliding form used to construct walls of 77-ft. pit. (Review) *Engineering News-Record* ... 186
—forms—Wall construction. (Review) *Engineering News-Record* ... 186
—scaffolds—Building construction. (Review) *Engineering News-Record* ... 536
—scaffolds speed cement plant. (Review) *Engineering News-Record* ... 536
Special cements—Laboratory investigations. (Review) Graf, Walz. *Zement* ... 88

SPECIFICATIONS

Standards—National technical and trade associations. (Review) *National Bureau of Standards* ... 481
Standardisation activities of national technical and trade associations. (Review) *Div. of Codes & Spec. Nat'l Bur. Stds.* ... 481
Steam-curing in concrete and lightweight-concrete products. (Review) *Beton-Stein Zeitung* ... 367
Steel floor slab forms produce "architectural" ceiling. (Review) *Engineering News-Record* 86
—requirement—Rectangular sections. (Review) Massarik. *Conc. & Const. Eng.* ... 365
Stress concentrations in plates loaded over small areas. (Review) Westergaard. *Proc. Am. Soc. C. E.* ... 539

Structural problems in bomb protection. (Review) Wessman and Rose. *Engineering News-Record*..... 186
Structure of hydrated portland cement. (Review) Tavasci. *Zement*..... 87
—Hydrated portland cement. (Review) Tavasci. *Zement*..... 87
Studies in the system CaO-$5CaO.3Al_2O_3$-CaF_2. (Review) Eitel. *Zement*..... 85
Substitute cements—Conservation of coal. (Review) Bergstrom. *Teknisk Tidskrift*... 89
Sulfate resistance of portland cements. (Review) *Technical News Bulletin of the National Bureau of Standards*..... 367

SURFACES

Floor finish—White cement. (Review) *Engineering News-Record*..... 535
Swedish substitute cement to conserve coal. (Review) Bergstrom. *Teknisk Tidskrift*... 89
Swimming pool—Built in a lake. (Review) *Engineering News-Record*..... 187
—tank built in a lake. (Review) *Engineering News-Record*..... 187

T

TESTS OF MEMBERS AND COMPLETED STRUCTURES

Beams—Repeated loadings—Fatigue. (Review) Len. *Struct. Engr*..... 88
—Strength and deflection. (Review) Suenson. *Ingen. Skrifter*..... 188
Bomb shelters. (Review) *Engineering News-Record*..... 538
Bridge—Cellular. (Review) Panhorst. *Engineering News-Record*..... 85
—Extensometer measurements. (Review) Smith, Lillard. *Proc. Am. Soc. C. E*..... 188
Treated cement—Effect on durability. (Review) Swayze. *Engineering News-Record*.. 87
Trends in concrete highway design. (Review) Anderson. *Engineering News-Record*..... 533
Tunnel lining—World's longest. (Review) *Engineering News-Record*..... 365
Types of powdered stone in concrete road construction. (Review) Weber. *Betonstrasse*. 369

U

Unit layer method of proportioning. (Review) Witt. *Rock Products*..... 481

W

Warehouse designed to speed construction. (Review) *Engineering News-Record*..... 538
War-time buildings—three-pin portal frames. (Review) *Concrete and Constructional Engineering*..... 367
Welding reinforcing—Bridge piers. (Review) *Engineering News-Record*..... 86
White cement floors for better light. (Review) *Engineering-News-Record*..... 535